Twiss Air Service 503-861-1214 1270 S.E. Flightline Dr.	ating and Certificate Number of Technician or Repair		RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Warrenton, Or 97146 05/25/07 Cessna 172K S/N+17258481 Tach 329 TT 3563		から	18,200	(')	Took	365
Completed annual inspection, updated AD compliance report dated		4	,		7.4.4	Completed 50 hr inspection / certify that
——05/25/07. Lubed aircraft per service manual. Installed hobbs meter and pressure switch in oil pressure line, wired to fuse at battery						this air not her her mounted and approved
box. Installed four station intercom system. I certify that this aircraft has been inspected in accordance with an annual inspection						on return to service
and was determined to be airworthy this date.						A'sPI
John Twiss A&P						
,						Twiss Air Service 503-861-1214
I CERTIFY THAT THE ALTIMETIR AND/OR LICERTIFY THAT	HE TRANSPONDER SYSTEM					1270 S.E. Flightline Dr. Warrenton, Or 97146
STATIC SYSTEM TESTS REQUIRED BY FAR TESTS REQUIRED	SY FAR 91.413 HAVE BEEN					04/01/08 Cessna 172K serial #17258481 Tach 416 TT 3650
91.411 HAVE BEEN FERFORMED IAW FAR #3 PERFORMED IAW	FAR 43 APP. F.		_			Completed annual inspection, updated AD compliance report dated
APP, E. TRANSPONDER	AT 190 5/0 1542/					04/01/08. Lubed aircraft per service manual. I certify that this aircraft has been inspected in accordance with an annual inspection and was
TESTED TO 2000 C FT. ON 6 2007	3/0 50150 Justa					determined to be airworthy this date.
011 (18/1/7)	NCE INC. JOERESSIN					John Twiss A&P

Date	Time Run		Total Time Since Overhaul		DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS.	Signature
	řírs.	Mins.	Hrs.	Mins.	& MINOH ADJUSTMENTS	**
Brought Forward		-				
						
		ļ				
	Ţ		. /,			
	۸.				2	
					·	
. ,,,,						
*************************				Twiss Air : 1270 S.E. I	Stobiling The	
******************************				MANUAUS E	Or 97[46] Sessia 172K script #1725848) Tuch 416 TT 3650	
	,		L	Commission	2000 1 1241	
				14/01/08. I	annual aspection tydated AD compliance upon dated aspection by Western Propeller AD 2006-18-15. I certify that has been inspected in necondary with a 18-18-18 certify that has been inspected in necondary with a 18-18-18	
fotel his page			11	urj was ger	in has been inspected in secondance with an annual inspection remarks to be airworthy this date.	et .
Fotal from Prev. Sum'y.					ARP IA	
Total Since Mfg.			1		<u> </u>	•

Date	Time Aun		Total Time Since Overhaul		PERTAINING TO AIRWORTHINESS DIRECTIVES. SERVICE BULLETINS, SERVICE LETTERS,	Signature	
	Hrs. Mins.		Hrs. Mins.		& MINOR ADJUSTMENTS	•	
Brought Forward		-			-		
					·		
,							
					•		
				·	ş.		
					,		
	`						

Total this page						***************************************	
Total from Prev. Sum'y.	-		•				
Total Since Mtg			1			19	

PA	RTIALR	EPAIR TA	<u>\G</u>	
OUNTTY PASTAGED 2	YK-IBF	1045(1)		
CUSTOMER		SERUAL	77732090	= -
work or 2007/3		GEN HOMELE	to a f	ma_
CUSTOMER ORDER NO.		- -	101/08	37 m/k
SACHARD RECEIVED PROTOR			т нцивен	
F.A. A. Approved S	6 A	1510 Post	N.W. North Perim land-Troutdate Att	eter Rd.
WESTERN AIRCR	AFT	Tros	dale, OR 97060 / / /	£
PROPELLERS INC		License		5,5 1.0_

9	Twiss Air Service 503 1270 S.E. Flightline Dr.	-861-1214		ns, Tests, Repairs and Alterat Name, Rating and Certificate Numbe See back pages for other specific entr	r of	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
	Warrenton, Or 97146 05/25/07 Cessna 172K S Engine Lycoming O-360-			· .						
	Completed annual inspect	ion updated A	AD compliance report dated inders were 76/80. Cleaned		 .					
	 fuel and oil screens. Clear 	ned and gapp	ed spark plugs. Removed r and test run on test bench.							
	Propeller governor remove reinstalled. I certify that	ed for overhan	ul by Wings West, and							
	accordance with an annual	inspection a	nd was determined to be		- }					
_				·	!					
	John Twiss A&P	IA		,						
			Twiss Air Service 503-86 1270 S.E. Flightline Dr.	61-1214						
			Warrenton, Or 97146 04/01/08 Cessna 172K seria	1#17258481 Tach 416 TT 3650						
			Engine Lycoming O-360-A17 Completed annual inspection	A SNL-14879-36A TTSOH 1198	!			-		
			and oil screens. Cleaned and	gapped spark plugs Legatify that this			+			
			was determined to be airworth	accordance with an annual inspection and hy this date.	,					
			John Twiss A&P	A						
ASA _										
		·· —			T.					
										10 (1997) (1997) ***
							* *	7		
. 2	10000000000000000000000000000000000000	\$						٠٠٠. 	23 k 1/2 8 1 2 1 1 2 2 1	
y y dri	She will be have the total	42				b		*		
		7. E	7. 7.846 97							
		· 李 · · · ·			in district.					